

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER  
COLO  
30-GOLDY  
IAE-

ROCKY FLATS PLANT,  
SOURCE CALIBRATION LABORATORY  
(Rocky Flats Plant, Building 126)

HAER No. CO-83-AE

Located between Second and Third streets and Central and Cedar avenues.

Golden Vicinity  
Jefferson County  
Colorado

Photograph CO-83-AE-1 taken by Timothy McGrath and Katherine T. Abeya, Source One, site photography contractor, January 1998.

CO-83-AE-1      VIEW OF BUILDING 126, LOOKING NORTH. BUILDING 126, THE SOURCE CALIBRATION LABORATORY, WAS USED TO EXPOSE AND CALIBRATE RADIATION DETECTION DEVICES, INCLUDING THERMOLUMINESCENT DOSIMETERS, WORN BY EMPLOYEES TO DETECT RADIATION EXPOSURE.